

CITY OF SPRINGFIELD
INTER-OFFICE MEMORANDUM

ATTENTION OF _____ FILE _____

DATE _____ May 24, 1982 _____

DEPARTMENT _____

On Monday, May 17th, 1982, Gene Pabst and myself investigated a complaint by Trinity Missionary Church, (2436 Neergard), about solvents being washed on their property by Dancey Collision Repair (2615 E. Kearney).

Upon visiting the site the said complaint was found to be true. Mr. Dancey was informed that he was in violation of city code and he was asked to take measures to prevent future spillage of solvents.

This office will keep the area in question under surveillance.

~~2436 NEERGARD~~ SIGNED _____ J. D. Slaughter
2615 E - KEARNEY

City of Springfield
Water Pollution Control Section
Pollution Complaint/Report Form

Date 10/15/91

Report From:

- ☒ Citizen
☐ Fire Dept.
☐ Public Information Office
☐ Health Department
☐ Other _____

Received By: R. LYMAN

Referred To: G. PAOST

Date of Incident: 9/17/91

ORIGINAL REPORT DATE

Complainant Information:

Name MR. LENS WALKER
Address 2440 N. NEERGAARD
Phone 865-6036 H 864-7550 W
Directions (if needed): _____

Responsible Party Information:

Name DANCEY COLLISION REPAIR INC.
Address 2615 E. KEARNEY 65883
Phone 864-4040

Possible contamination of: ☐ soil ☐ groundwater
☒ surface water what body? _____
☐ other _____

Other pertinent information: _____

Who to contact: 895

- ☐ DNR 417-~~837~~-6950
☐ DNR 314-634-2436
☐ EPA 913-236-3778
☐ Fire Dept. 864-1719
☐ Police Dept. 864-1719
☐ Bob Schaefer
☐ CU 831-8320
☐ Street Dept.

- ☐ Health Dept.
☐ Sewer Maintenance
☐ Sewer Construction
☐ Chemtrec 1-800-424-9300
☐ DOT
☐ NRC 1-800-424-8802
☐ Other _____

Details of incident: SEE PIO COMPLAINT ATTACHED.

Action needed: INSPECT FOR RUNOFF, POLLUTANTS OF
CONCERN.

(over)

ADDRESS 2615 E. KEARNEY

2615 E. Kearney

Investigation Results

On 10-16-91 (1:45 P.M.) An inspection was made of the Area behind Dancey Collision Repair And the side of Trinity Missionary Church. No problem could be found. Only runoff from property onto Trinity Missionary Church would be lot runoff or from roof drains At Dancey Collision. We could find no improper storage of Any materials that could cause A problem.

Gene Pabst

COMPLAIN REPORT
FROM: KAY LOGSDON-PUBLIC INFORMATION OFFICE
864-1011

RECORD NO: 956
STATUS: ACTIVE
REPORT DATE: 09/17/91
TICKLER DATE: 10/30/91
TYPE OF COMPLAINT: GUIDELINES

COMPLAINANT: Mr. Lens Walker

ADDRESS: 2460 North Neergard

CITY/STATE/ZIP: Springfield MO 65803

HOME PHONE: 865-6036 WORK PHONE: 869-7550

ADDRESS OF PROBLEM: 2615 East Kearney

SITUATION: Complainant indicated that there had been several problems over the past few years with the business (Dancey Collision Repair Inc.) located at the above address. There are two things he would like the city to check on. 1) last night about 6:10 p.m. he noticed what he thought was smoke coming from a vent on the north side of the repair shop and thought it was on fire. Thinks they were cleaning out their filters with some kind of chemical and he wants to know what it was - could cause damage to the church buses and also could be a health problem. 2) boxes, fenders, doors, etc. stacked on the north side of the building and wants them removed -- its a mess. PIO routing to Health.

DEPARTMENT REFERRAL 1: HEALTH
DEPARTMENT REFERRAL 2: PUBLIC WORKS
DEPARTMENT REFERRAL 3: NONE
DEPARTMENT REFERRAL 4: NONE

FOLLOW UP: 9-24-91 Ron Boyer reported they checked vent & found no violations. Company replaced filter 8-8-91. Vector people looking at storage. PIO routing to Joe Harman so he'll have a copy of report. Health reports Mr. Dancey couldn't think of anything that was done differently that would have caused the smoke. Health said new filters bought and in place 8-8-91. See page 2.

FOR PIO USE ONLY

RESOLVED DATE:

ZONE: 2 Councilman Mac McCartney

ACKNOWLEDGEMENT LETTER SENT: 09/17/91
STATUS LETTER SENT:
STATUS LETTER SENT:
ABATEMENT LETTER SENT:

To: Bob Schaefer
Have Randy Lyman
check the area to see if
we can determine any
problem that be caused
by improper removal.
Bob T
10/11/91

ADDITIONAL ACTION:

Health investigated 9-23-91, complaint not justified. No trash, dumpster was clean; auto parts behind the bldg. but does not constitute a violation. Business is zoned correctly & has a 6 ft. chain link fence around it. 10-91 Mr. J. Dan Woodall forwarded photographs of area Mr. Cumley; PIO has contacted DNR about an area of the church property that does not grow grass; Mr. Walker believes there may be something coming from collision company causing the problem. PIO contacted DNR (Chuck Craiger) 10-2-91 who is to check on this & get back to us. 10-8-91 Mr. Walker advised PIO fumes from vent still a problem in the church. Said several years ago in a meeting with Health, etc. that Dancey had agreed to relocate the vent but hasn't moved it. PIO routing to Health (Ron Boyer) to advise of Mr. Walker's request for a meeting as soon as possible & to check on the relocation of the vent.

10/11/91
Bob -
Cause Dan was area checker
out for possible runoff problems.
It may be Dancey should direct
runoff to another area. (Area is
between Dancey Collision and
Primarily Missionary Church.)
Jane